

1/11
H-409
Goldman




FIG. 1

2/11
H-409




FIG. 2

3/11
H-409




FIG. 3





FIG. 4

FIG. 5



H-409
5/11

6a/11
H-409




FIG. 6a

6b/11
H-409




FIG. 6b




FIG. 7.

8/11
H-409

80




FIG. 8

9/11
H-409




FIG. 9




FIG. 10.




FIG. 11.




FIG. 12a.




FIG. 12b.




FIG. 13.

FIG. 14a.




FIG. 14b.




FIG. 15a.




FIG. 15b.






FIG. 16